Jurisdiction	Туре	Machine	# of pieces	Age	Functionality	Letter
Adams	In Precinct Scan Central Count Scan ADA/Touchscreen Component	M100 M100 AutoMArk	36 5 14 Years	11 to 16 years 16 years	Good Routine maintenance on each machine on a yearly basis. Routine maintenance on each machine on a yearly basis. Good	Yes
Alexander						No
Bond	In Precinct Scan ADA/Touchscreen Component	AccuVote OS 1.96.6C AccuVote TSx 4.6.4D	24 22	15 13	Functioning with intermittent problems Functioning with intermittent problems	Yes
Boone	In Precinct Scan ADA/Touchscreen Component	AccuVote OS 1.96.6C AccuVote TSX 4.6.4	43 42	Oct-03/Dec- 13/Oct-18 1-Jan		Yes
Brown	In Precinct Scan ADA/Touchscreen Component	DS200 ExpressVote	15 14	Jan-18 Jan-18		Yes
Bureau	OpenElect 2.0 In Precicnt Scan ADA/Touchscreen Component	OVO 2.0 OVI 2.0	45 45	3yrs 3yrs		Yes
Calhoun	In Precinct Scan ADA/Touchscreen Component	M100 5.4.4.58 Automark 1.3.2907	8 6	7,8,13 13	Good with minor repairs and yearly maintenance Good with minor repairs and yearly maintenance	Yes
Carroll	In Precinct Scan ADA/Touchscreen Component	Accuvote OS 1.96.6 Accuvote TS 4.6.4	27 26	2,16 13	Good Good	Yes
Cass	In Precinct Scan ADA/Touchscreen Component	Accuvote Accuvote TSX	13 5 16	14 9 14	Good Good Good	Yes
Champaign	In Precinct Scan ADA/Touchscreen Component	M100 AutoMark DS200	116 118 16	2010 2008/2016 2013/2015	Good Good Good	No
Christian	In Precinct Scan ADA/Touchscreen Component GEMS 1.18.24	AccuVote OS 1.96.6c AccuVote TSx 4.6.4D	40 40	16 years 14 years	Functioning w/ Intermittent Problems Functioning w/ Intermittent Problems	Yes
Clark	In Precinct Scan ADA/Touchscreen Component	Open Elect Voting Optical Scan (OVO) Open Elect Voting Interface (OVI) 2.0	18 36	3 3	New and working New and Working	Yes
Clay	In Precinct Scan ADA/Touchscreen Component	M100/5.4.4.5 Firmware;1.3 Hardware Automark/1.3.2907 Firmware;1.3 Hardware	28 16	12-13 13	Good Good	Yes
Clinton	In Precinct Scan ADA/Touchscreen Component Electronic Ballor Marking Device	Optical Scan TSX Express Vote/5.3.1.0	51 43 2	15 13 1	Aging Aging New	Yes
Coles	In Precinct Scan ADA Touchscreen Component	Open Elect Voting Optical Scan (OVO)/ 2.0 Freedom Vote Tablet (FVT)/2.0	32 64	1 1	New New	Yes
Cook	In Precinct Scan Central Count Scan ADA/Touchscreen Component ADA/Touchscreen Component Electronic Ballot Marking Device ICX Prime Touchscreen ICX Prime Accepted Electronic Ballot Marking Device	Insight Scanner/K2.16 Imagecast Central/5.6A Edge 2 Plus/1.2.77 Edge 2 Plus/1.2.77 HP 402dne BMD Printer/5.6A ICX Prime/5.6A ICX Prime/5.6A HP 402dne BMD Printer/5.6A	1599 4 3200 700 394 394 2256 2256	13 Years 6 Months 13 Years 13 Years 6 Months 6 Months 6 Months 6 Months	Election Day Ballots - Use Gen 2018 & April 2019 Mail in Ballots/OUCAVA - Use Gen 2018 & April 2019 Digital Tabulator - Use Gen 2018 & April 2019 Digital Tabulator - Use Gen 2018 & April 2019 - Early Voting Ballot Marking Device Use with ICX Prime Touchscreen - April 2019 Touchscreen use with Ballot Marking Device - April 2019 Have not been use for any Election Have not been use for any Election	Yes

to all all all a	T	Marking	# -f -:		For additional life.	Latter
Jurisdiction	Туре	Machine	# of pieces	Age	Functionality	Letter
Crawford	In Precinct Scan	AccuVote 1.96.6C	30	3-15	Good	Yes
			1	3-15	Inoperable	
	ADA/Touchscreen Component	AccuVote TS-4.6.4	21	13	Good	
Cumberland	In Precinct Scan	AccuVote-1.96.6C/GEMS-1.18.24	17	9-15	Good	Yes
	ADA/Touchscreen Component	AccuVote TS-4.6.4	2 11	15 13-14	Broken Good	
	Abry Touchscreen component	Accuvote 13 4.0.4		13 14	0000	
DeKalb	In Precinct Scan	M100/5.4.45	71	8-12	Good	Yes
		DS200/1.7.10	9	3	Good	
	ADA/Touchscreen Component	AutoMark/1.3.2907	55	12	Good	
DeWitt	In Precinct Scan	Open Elect Voting Optical Scan (OVO) / 2.0	20	less than a year	New equipment and working properly	Yes
	ADA/Touchscreen Component	Freedom Vote Tablet (FVT) / 2.0	20	less than a year	New equipment and working properly	
	Electronic Ballot Marking Device	Freedom Vote Tablet (FVT) / 2.0	20	less than a year	New equipment and working properly	
Douglas	OpenElect 2.0	ovo	20	1	Functions as required	Yes
		FVT	20	1	Functions as required	
DuPage	In Precinct Scan	Accuvote OS Tabulator 196.6.C	631	19	Good	Yes
			339	19	Broken	
	ADA/Touchscreen Component	Accuvote TSX 4.6.4	630	13	Good	
		Accuvote TSX 4.6.5	122	13	Broken	
Edgar	In Precinct Scan	Open Elect Optical Scan OVO V2.0	14	6 Months	Excellent	Yes
	Central Count Scan	OVO V2.0		6 Months	Excellent	
	ADA/Touchscreen Component	Freedom Vote Tablet FVT V2.0		6 Months	Excellent	
Edwards	In Precinct Scan	Model 100(M-100)-5.4.4.5	9	13	Fine	No
Lawaras	Electronic Ballot Marking Device	Automark-1.3.2907	7	13	Fine	
Effingham	In Precinct Scan	Model 100(M-100)-5.4.4.5	41	13	Early Voting and Election Day Precinct Scanner.	Yes
	ES\$ S DIGITAL SCAN DS200	Digital Scan Ds2001.7.0.0	2	6	Early Voting and Election Day Precinct Scanner.	
	ADA/Touchscreen Component	Automark-1.3.2907		13	ADA Machine for early Voting \$ Election Day Voting	
Fayette	In Precinct Scan	Accuvote	64+	20+	Not good	Yes
	ADA/Touchscreen Component	Accuvote	64+	20+	Not good	
Ford	In Precinct Scan	Accuvote	20	11-16	Good	Yes
	ADA/Touchscreen Component	TSX Touchscreen	21	11-13		
		13A TOUCHSCIECH	21	11-13	Good	
For a letter	In Burningh Cons					V
Franklin	In Precinct Scan	GEMS 1.18.24.101	50	21	Extremely Bad	Yes
Franklin	In Precinct Scan Electronic Ballot Making Device					Yes
Franklin Fulton		GEMS 1.18.24.101	50	21	Extremely Bad	Yes
	Electronic Ballot Making Device In Precinct Scan	GEMS 1.18.24.101 AutoMark AccuVote 1.96.6C AccuVote TS 4.6.4	50 35 88 90	21 19 20+ 14	Extremely Bad Needs Replaced Excellent Excellent	
	Electronic Ballot Making Device	GEMS 1.18.24.101 AutoMark AccuVote 1.96.6C	50 35	21 19 20+	Extremely Bad Needs Replaced Excellent	
	Electronic Ballot Making Device In Precinct Scan	GEMS 1.18.24.101 AutoMark AccuVote 1.96.6C AccuVote TS 4.6.4	50 35 88 90	21 19 20+ 14	Extremely Bad Needs Replaced Excellent Excellent	
Fulton	Electronic Ballot Making Device In Precinct Scan ADA/Touchscreen Component	GEMS 1.18.24.101 AutoMark AccuVote 1.96.6C AccuVote TS 4.6.4 Accuvate TS 4.6.4	50 35 88 90 45	21 19 20+ 14 14	Extremely Bad Needs Replaced Excellent Excellent Excellent	Yes
Fulton	Electronic Ballot Making Device In Precinct Scan ADA/Touchscreen Component In Precinct Scan	GEMS 1.18.24.101 AutoMark AccuVote 1.96.6C AccuVote TS 4.6.4 Accuvate TS 4.6.4 M-100-Firmware 5.4.4.5	50 35 88 90 45	21 19 20+ 14 14	Extremely Bad Needs Replaced Excellent Excellent Excellent All work well with new batteries in 2018	Yes
Fulton Gallatin	Electronic Ballot Making Device In Precinct Scan ADA/Touchscreen Component In Precinct Scan Electronic Ballot Making Device Central Count Scan	GEMS 1.18.24.101 AutoMark AccuVote 1.96.6C AccuVote TS 4.6.4 Accuvate TS 4.6.4 M-100-Firmware 5.4.4.5 AutoMARK-Firmware-1.3.2907 M-100-Firmware 5.4.4.5	50 35 88 90 45 11 12 1	21 19 20+ 14 14 14 14	Extremely Bad Needs Replaced Excellent Excellent Excellent All work well with new batteries in 2018 ADA compiant-works well Works well with new batteries in 2018	Yes Yes
Fulton	Electronic Ballot Making Device In Precinct Scan ADA/Touchscreen Component In Precinct Scan Electronic Ballot Making Device Central Count Scan In Precinct Scan	GEMS 1.18.24.101 AutoMark AccuVote 1.96.6C AccuVote TS 4.6.4 Accuvate TS 4.6.4 M-100-Firmware 5.4.4.5 AutoMARK-Firmware-1.3.2907 M-100-Firmware 5.4.4.5 AccuVote 1.96.6	50 35 88 90 45 11 12 1	21 19 20+ 14 14 14 14 14 14 average 10yr	Extremely Bad Needs Replaced Excellent Excellent Excellent All work well with new batteries in 2018 ADA compiant-works well Works well with new batteries in 2018	Yes
Fulton Gallatin	Electronic Ballot Making Device In Precinct Scan ADA/Touchscreen Component In Precinct Scan Electronic Ballot Making Device Central Count Scan	GEMS 1.18.24.101 AutoMark AccuVote 1.96.6C AccuVote TS 4.6.4 Accuvate TS 4.6.4 M-100-Firmware 5.4.4.5 AutoMARK-Firmware-1.3.2907 M-100-Firmware 5.4.4.5	50 35 88 90 45 11 12 1	21 19 20+ 14 14 14 14 14 14 average 10yr average 10yr	Extremely Bad Needs Replaced Excellent Excellent Excellent All work well with new batteries in 2018 ADA compiant-works well Works well with new batteries in 2018	Yes
Fulton Gallatin	Electronic Ballot Making Device In Precinct Scan ADA/Touchscreen Component In Precinct Scan Electronic Ballot Making Device Central Count Scan In Precinct Scan	GEMS 1.18.24.101 AutoMark AccuVote 1.96.6C AccuVote TS 4.6.4 Accuvate TS 4.6.4 M-100-Firmware 5.4.4.5 AutoMARK-Firmware-1.3.2907 M-100-Firmware 5.4.4.5 AccuVote 1.96.6	50 35 88 90 45 11 12 1	21 19 20+ 14 14 14 14 14 14 average 10yr	Extremely Bad Needs Replaced Excellent Excellent Excellent All work well with new batteries in 2018 ADA compiant-works well Works well with new batteries in 2018	Yes Yes

Jurisdiction	Туре	Machine	# of pieces	Age	Functionality	Letter
Hamilton	In Precinct Scan	Unity 3.4.1.1 -Optical/Digital Scan Tabulation	16	13	Election Day Precinct Scanner. Early Voting Precinct Scanner	Yes
	Central Count Scan	Model 100-5.4.4.5	2	13	The M100 serves as the Central County Scanner to process all mail out Absentee ballots	
	ADA/Touchscreen Component	Automark-1.3.2907	17	13	The Automark serves as the ADA Machines for Early Voting and Election Day.	
Hancock	In Precinct Scan	M100/5.4.4.5	37	14	Fine	Yes
	Electronic Ballot Marking Device	AutoMarks/1.3.2907	29	15	Fine	
Hardin	In Precinct Scan	Open Elect Voting Optical Scan OVO/2.0	8	1	New	Yes
	ADA/Touchscreen Component	Freedom Vote Tablet/2.0	14	1	New	
Henderson	In Precinct Scan	M100/2004 Series	15	15	Fine	Yes
richaerson	ADA/Touchscreen Component	Automark	13	14	Slow and Finicky	103
Henry	In Precinct Scan	Accu-Vote OS Device	42	16 13	good	No
	ADA/Toucscreen Component	TSX Device	36	13	good	
Iroquois	In Precinct Scan	Accu-Vote OS Device	38	16	Good	Yes
		Accu-Vote OS Device	2	6	Good	
		Accu-Vote OS Device	1	2	Good	
		TSX Device	31	13	Good	
Jackson	In Precinct Scan	TSX Device	10		Good	No
	ADA/Touchscreen Component	Automark	56		Good	
Jasper	In Precinct Scan	AccuVote 1.96.6	18	21	These are in current working order and were used in the last election.	Yes
Jaspei	In Precinct Scan	AccuVote 1.96.6	23	21	Not sure how many of these are in working order but have enough for elections.	res
	ADA/Touchscreen Compnonent	Accuvote TSX 4.6.4	25	13	Not all are in functioning order but have enough for elections.	
					_	
Jefferson	In Precinct Scan	DS200 Digital Scanners AutoMarks	37 38	2 14	Fine Fine	Yes
	ADA/Touchscreen Component	Autowarks	30	14	riile	
Jersey	In Precinct Scan	DS200 2.17.0.2	17	1-6	Excellent	Yes
	ADA/Touchscreen Component	AutoMark 1.8.7.0	9	15	Fair to poor condition	
		ExpressVote 2.4.0.2	8	1	Excellent	
JoDaviess	In Precinct Scan	M100 Optical Scan Version 5445	34	14	Good	Yes
	Electronic Ballot Marking Device	AutoMark. Version 1.3.2907	25	13	Average	
Johnson	GEMS 1.18.24	AccuVote OS 1.96.6C	18	14		Yes
Johnson	GEIVIS 1.10.24	Accuvote OS 1.90.0C	17	14		res
Kane	Central Count Scan	Tally/4.3.1.0	1	12	Fine	Yes
	ADA/Touchscreen Component Electronic Ballot Marking Device	Eslate DAU 5000/4.21.3 Eslate 300/4.21.3	429 993	12 12	Fine Fine	
Kankakee	In Precinct Scan	Accuvote-OS 1.96.6	82	15	Functional with minor issues	Yes
	ADA/Touchscreen Component	Accuvote-TSX 4.6.4D	89	12	Functional with sporadic calibration issues	
Kendall	In Precinct Scan	M100/5.4.4.5	83	6-13	Good	Yes
		DS200	5	1	Good	
	ADA/Touchscreen Component	AutoMark/1.3.2907 (-2911)	54	6-13	Good	
Knox	In Precinct Scan	AccuVote OS-1.96.6C	29	16	Good	Yes
MIOA	ADA/Touchscreen Component	AccuVote OS-1.96.6C AccuVote TS-4.6.4	31	13	Good	162
Lake	In Precinct Scan	DS200 v. 2.13.1.0	274	3-5yrs	in good working order	Yes
	Central Count Scan ADA/Touchscreen Component	DS850 v. 2.10.1.0 ExpressVote v. 2.3.2/AutoMark v. 1.8.60	1 117/194	3 1.5-3/13yrs	in good working order in good working order	

Jurisdiction	Туре	Machine	# of pieces	Age	Functionality	Letter
LaSalle	In Precinct Scan	M100	149	2003-2008	fair, good/used	Yes
Lasanc	Electronic Ballot Marking Device	Automark	105	11/15/2005	fair	
Lawrence	In Precinct Scan	M100-Firmware 5.4.4.5	26	16	Scanner and Tabulation Unit	Yes
	Central Count Scan	M100-Firmware 5.4.4.5	1	16	Tabulation Unit	
	ADA/Touchscreen Component	AutoMARK-Firmware-1.3.2907	25	14	ADA compliant	
Lee	In Precinct Scan	AccuVote OS-1.96.6	33	15	Good	Yes
	ADA/Touchscreen Component	AccuVote TS-4.6.4	47	13	Good	
Livingston	In Precinct Scan	AccuVote OS 1.96.6c	41	16	Functioning with intermittent problems	Yes
Livingston	ADA/Touchscreen Compnonent	AccuVote TSX 4.6.4D	61	14	Functioning with intermittent problems	163
				=:		-
Logan	In Precinct Scan	M100 5.4.4.5	35	14 years	Good working condition, a few needing repairs	Yes
	ADA/Touchscreen Compnonent	AutoMark 1.3.2907	30	14 years	Good working condition, most need repair	
	Unity 3.4.1.1					
Macon	In Precinct Scan	Open Elect Voting Optical Scan (OVO)	46	3 yrs	New Equipment and working properly	Yes
	Electronic Ballot Marking Device	Open Elect Voting Interace (OVI)/ 2.0	60	3 yrs	New Equipment and working properly	
Macoupin	Unisyn Open Elect / 2.0 In Precinct Scan	AccuVote Os	58	15 yrs	Usable but either needs replacement or new system	Yes
Macoupin	ADA/Touchscreen Compnonent	AccuVote TSX	55	15 yrs	osable but either needs replacement of new system	163
	GEMS	Accurate 13A	33	15 yı3		
Madison	In Precinct Scan	M100	247	20	maintenance intensive	Yes
	Central Count Scan	DS200	23	6	maintenance intensive	
	ADA/Touchscreen Component	AutoMark 1.3.2907	204	15	tend to jam a lot	
				13-15/New		
Marion	In Precinct Scan	AccuVote	34	Used	In Working Condition	Yes
GEMS/1.18.24	ADA/Touchscreen Component	TSX	39	14/ New Used	In Working Condition	
Marshall	In Precinct Scan	M-100/5.4.4.5	18	15	Good	Yes
iviaisiiaii	ADA/Touchscreen Component	Automark 1.3.2907	14	15	Good	163
	ADAy Touchscreen component	Automark 1.3.2507	1	15	Used for parts only	
Mason	In Precinct Scan	Open Elect Voting Optical Scan (OVO)	18	1	New equipment and working properly	Yes
	ADA/Touchscreen Component	Freedom Vote Tablet (FVT)	18	1	New equipment and working properly	
Massac	In Precinct Scan	AccuVote 1.96.6E	19	?	All work properly	Yes
	ADA/Touchscreen Component	AccuVote TS-4.6.4	19	?	All work properly	
McDonough	In Precinct Scan	AccuVote 1.96.6c	22	New in 1999	Good	Yes
	ADA/Touchscreen Component	AccuVote TS - 4.6.4	34	sed used don't kn	Good	
	,		-			
McHenry	In Precinct Scan	DS200-2.17.0.1	166	9 months	New and still under warranty	No
	ADA Touchscreen/Electronic BMD	ExpressVote-2.4.0.1	300	9 months	New and still under warranty	
	EVS-Electionware-5501					
	Electionware-4.8.0.1					
	Election Reporting Manager-8.13.0.1					
	Express Link-1.3.0.0					
McLean	In Precinct Scan	AccuVote 1.96.6C	79	9-15	Fair	Yes
	ADA/Touchscreen Component	AccuVote TS 4.6.4	89	3-13	Fair	
	· · ·					
Menard	In Precinct Scan	Model 100-5.4.4.5	12	13 years	Early Voting and Election Day Precinct Scanner.	Yes
Unity 3.4.1.1 -						
Optical Scan						
Tabulation	Central Count Scan	Model 100-5.4.4.5	1	13 years	Used as the Central Count Scanner to process Absentee and Mail out ballots.	
	ADA/Touchscreen Component	Automark-1.3.2907	10	13 years	The Automark serves as the ADA Machines for Early Voting and Election Day.	
Mercer	In Precinct Scan	M100	25	13 years	Still working, but not sure how much longer	Yes
ty ERM / 7.9.1.0	Electronic Ballot Marking Device	M100 Auto Mark	25 25	13 years 13 years	Still working, but not sure now much longer Still working for the most part; starting to have trouble with the touch screens	162
ALY LINIVI / 7.3.1.U	Lieutonic ballot ivial king Device	Auto Iviai k	23	15 years	July working for the most part, starting to have trouble with the touch screens	

Jurisdiction	Туре	Machine	# of pieces	Age	Functionality	Letter
Monroe						No
Montgomery	In Precinct Scan	M100	51	05,06,17,18	Good	Yes
	Electronic Ballot Marking Device	Automark	35	05,06,12,16,18	Good	
Morgan	In Precinct Scan	Accuvote OS 1.96.6C	53	11 years	Good/Fair	Yes
. 0-	ADA/Touchscreen	Accuvote TS 4.64 (TSX)	39	11 years	Good/Fair	
						<u> </u>
Moultrie	In Precinct Scan	Unisyn OVO 2.0	14	3 yrs.	Great	Yes
	Electronic Ballot Marking Device	Unisyn OVI 2.0	24	3 yrs.	Great	
Oale	In Draginat Coop	DS 200 / 1.7.1.0	1	1.1/2	Cond working condition	Vos
Ogle	In Precinct Scan In Precinct Scan	M 100 / 5.4.4.5	46	1 1/2 yrs 3-16 yrs old	Good working condition Good working condition/ Re-conditioned equipment	Yes
	Electronic Ballot Marking Device	AutoMark / 1.3.2907	46	3-16 yrs old	dood working conditions re-conditioned equipment	
	Electronic bande marking bevice	Automatic Fioresor		5 20 715 010		
Peoria	ADA/Touchscreen Component	eSlate	579	14	Good	No
	Central Count Scan	Ballot Now 3.3.11	1	14	Good	
_						
Perry						No
Piatt	GEMS 1.18.24					Yes
	In Precinct Scan	ACCUVOTE OS	22	2003	Regular Preventive Maint.performed - good to fair	
	ADA/Touchscreen Component	ACCUVOTE TS	17	2006	Regular Preventive Maint.performed - good to fair	
Pike	In Precinct Scan	Accuvote OS 1.96.6	26	2005	excellent	No
	Electronic Ballot Marking Device	Accuvote TS-4.6.4	25	2005	excellent	
Pope	In Precinct Scan	AccuVote 1.96.6E (?)	8	2003	Fair	Yes
Торс	ADA/Touchscreen Component	TSX	6	2006	Good	163
	, <u>,</u>					
Pulaski						Yes
RM 8.12.2.0	In Precinct Scan	DS200 2.13.1.0	9 Units	2 years old	Functionality - Good	
	In Precinct Scan	DS200 2.13.1.0	1 Unit	2 years old	Functionality - Good	
	Electronic Ballot Marking Device	Expressvote 1.4.1.0	10 Units	2 years old	Functionality - Good	
Putnam	In Precinct Scan	OVO 2.0				Yes
Putnam	In Precinct Scan Electronic Ballot Marking Device	OVO 2.0 OVI 2.0				Yes
	Electronic Ballot Marking Device	OVI 2.0				
Randolph	Electronic Ballot Marking Device System and Version Number	OVI 2.0				Yes
	Electronic Ballot Marking Device System and Version Number In Precinct Scan	OVI 2.0 1.18.24.101 Tabutor AccuVote	23	14	Work at this time	
	Electronic Ballot Marking Device System and Version Number In Precinct Scan Central Count Scan	OVI 2.0 1.18.24.101 Tabutor AccuVote Tabutor AccuVote	5	14	Work at this time	
	Electronic Ballot Marking Device System and Version Number In Precinct Scan	OVI 2.0 1.18.24.101 Tabutor AccuVote				
	Electronic Ballot Marking Device System and Version Number In Precinct Scan Central Count Scan	OVI 2.0 1.18.24.101 Tabutor AccuVote Tabutor AccuVote	5	14	Work at this time	
Randolph	Electronic Ballot Marking Device System and Version Number In Precinct Scan Central Count Scan ADA/Touchscreen Component	OVI 2.0 1.18.24.101 Tabutor AccuVote Tabutor AccuVote DRE/TSX Diebold	5 35	14 14 years	Work at this time Work at this time	No
Randolph Richland	Electronic Ballot Marking Device System and Version Number In Precinct Scan Central Count Scan ADA/Touchscreen Component In Precinct Scan ADA/Touchscreen Component	OVI 2.0 1.18.24.101 Tabutor AccuVote Tabutor AccuVote DRE/TSX Diebold Accuvote 1.96.6C Accuvote TS 4.6.4	5 35 21 16	14 14 years 13 13	Work at this time Work at this time Beginning to see signs of wear. Some have been retired	No Yes
Randolph Richland Rock Island	System and Version Number In Precinct Scan Central Count Scan ADA/Touchscreen Component In Precinct Scan ADA/Touchscreen Component In Precinct Scan	OVI 2.0 1.18.24.101 Tabutor AccuVote Tabutor AccuVote DRE/TSX Diebold Accuvote 1.96.6C Accuvote TS 4.6.4 AccuVote OS Optical Scan	5 35 21	14 14 years 13 13 2005	Work at this time Work at this time Beginning to see signs of wear. Some have been retired	No
Randolph Richland	Electronic Ballot Marking Device System and Version Number In Precinct Scan Central Count Scan ADA/Touchscreen Component In Precinct Scan ADA/Touchscreen Component	OVI 2.0 1.18.24.101 Tabutor AccuVote Tabutor AccuVote DRE/TSX Diebold Accuvote 1.96.6C Accuvote TS 4.6.4	5 35 21 16	14 14 years 13 13	Work at this time Work at this time Beginning to see signs of wear. Some have been retired	No Yes
Randolph Richland Rock Island	System and Version Number In Precinct Scan Central Count Scan ADA/Touchscreen Component In Precinct Scan ADA/Touchscreen Component In Precinct Scan	OVI 2.0 1.18.24.101 Tabutor AccuVote Tabutor AccuVote DRE/TSX Diebold Accuvote 1.96.6C Accuvote TS 4.6.4 AccuVote OS Optical Scan	5 35 21 16	14 14 years 13 13 2005	Work at this time Work at this time Beginning to see signs of wear. Some have been retired	No Yes

Jurisdiction	Туре	Machine	# of pieces	Age	Functionality	Letter
Sangamon	In Precinct Scan	M100 In-Precinct Scan/V. 5.4.4.5	150	10.5	Average	Yes
Sungamon	Central Count Scan	M650 Central Tabulator/V. 2.2.2.0	1	10.5	Average to Good	103
	ADA/Touchscreen Component	AutoMark/V. 1.3.2907	125	10.5	Average to Good	
Schuyler	In Precinct Scan	Accuvote 1.96.6C	27	90's,06,18	Fair, poor	Yes
	ADA/Touchscreen Component	Accuvote TS 4.6.4	21	06,16	Good	
Scott	In Precinct Scan	Accuvote OS/1.96.6C	7	16	Good	Yes
50011	mi reemer seam	Accuvate 05/1.50.0c	1	2	New	163
	ADA/Touchscreen Component	Accuvote TS/4.6.4	9	13	Good	
		·				
Shelby	In Precinct Scan	pen Elect Voting Optical Scan (OVO)/2	34	1	New and working properly	Yes
	ADA/Touchscreen Component	Freedom Vote Tablet (FVT)/2.0	30	1	New and working properly	
Stark	In Precinct Scan	M100/5.4.4.5	10	13	Fine	Yes
Stark	ADA/Touchscreen Component	Automark	9	13	Fine	165
	ADA/Touchscreen component	Automark	3	13	riile	
					So, So. We are having to change quite a few machines each year because the readers keep going	
St. Clair	In Precinct Scan	Accu-Vote 2000/1.96.6	260	15	out	No
	Central Count Scan	Accu-Vote 2000/1.96.6	11	15	Same as In-Precinct machines	
					Overall still work alright. Lose 2-4 each year because video cards go out. Can't get parts to fix these	
	ADA/Touchscreen Component	Accu-Vote- TSX/ 4.6.4.103	230	15	machines anymore	
Stephenson	In Precinct Scan	Automark	39			No
Stephenson	Tabulator Name/Version Number	Automark	4			NO
	, , , , , , , , , , , , , , , , , , ,		· · · · · · · · · · · · · · · · · · ·			
Tazewell	In Precinct Scan	Unisyn Open Elect / 2.0	80	1 year	New equipment and working properly	Yes
	ADA/Touchscreen Component	Freedom Vote Tablet (FVT) / 2.0	80	1 year	New equipment and working properly	
		Freedom Vote Tablet (FVT) / 2.0	80	1 YEAR	New equipment and working properly	
		/	4-7			.,
Union	In Precinct Scan	Accu Vote / 1.96.6	17	15 years	No Longer in Use	Yes
	Central Count Scan ADA/Touchscreen Component	Accu Vote / 1.96.4 TSX Touchscreen/ 4.6.4.103	1 17	15 Years 15 Years	No Longer in Use No Longer in Use	
	ADA/Touchscreen Component	15X Touchscreeny 4.6.4.105	1/	15 fears	NO LONGET IN OSE	
Vermilion	In Precinct Scan	AccuVote 1.96.6C	68	19	Poor, needs replaced soon	Yes
	ADA/Touchscreen	AccuVote TS-4.6.4	44	4-5	Good	
,						
Wabash	In Precinct Scan	M100/5.4.4.5 Firmware; 1.3 Hardware	28	12-13	Good	Yes
	ADA/Touchscreen Component	Automark/1.3.2907 Firmware;1.3 Hardware	16	13	Good	
Warren	In Precinct Scan	AccuVote 1.96.6C	18	2004/2007	Good	Yes
waiteii	ADA/Touchscreen Component	Accuvote T.5-0.0C	23	2004/2007	Good	ies
	ADAY TOUCHSCIPCTIC COMPONENT	Accurate 13 4.0.4	23	2003/2011	3000	
Washington	In Precinct Scan	AccuVote-1.96.6	23	12	Good	Yes
	ADA/Touchscreen Component	AccuVote TS-4.6.4	21	12	Fair	
Wayne	In Precinct Scan	AccuVote OS-2000; Release 1.96.6	21	At least 30	Functions but has needed parts replaced	Yes
-	ADA/Touchscreen Component	TS Diebold 2003-2005; BLR7-1.2.1	22	Not sure/old	Functions, but starting to have issues	
White	In Precinct Scan	AccuVote 1.96C	23	15	Good	Yes
	ADA/Touchscreen Component	TS 4.6	26	15	Good	
•						
Whiteside	In Precinct Scan	AccuVote OS 1.96.6C	43	14	Good	Yes
	ADA/Touchscreen Component	AccuVote TS 1.18.24	49	14	Good	
14711	In Desci. 1.5	DC200 1 C 2 2	22	_	r:	V-
Will	In Precinct Scan	DS200-1.6.0.0	80	6	Fine	Yes
	Central Count	Model 100-5.4.4.5 Model 650-2.2.0.0	420 1	12-16 12	Fine Fine	
	Electronic Ballot Marking Device	Automark-1.3.2907	1 374	12 14	Fine	
	Licetionic ballot Marking Device	Automark-1.3.2307	3/4	14	Time	

Jurisdiction	Туре	Machine	# of pieces	Age	Functionality	Letter
Williamson Unity 3.4.1.1 - Optical Scan	In Precinct Scan	Model 100-5.4.4.5	71	15 years	Early Voting and Election Day Precinct Scanner.	No
Tabulation	Central Count Scan	Model 100-5.4.4.5	1	15 years	Used as the Central Count Scanner to process Absentee and Mail out ballots.	
rabalation	Electronic Ballot Marking Device	Automark-1.3.2907	63	14 years	The Automark serves as the ADA Machines for Early Voting and Election Day.	
Winnebago	In Precinct Scan	Unity 3.4.1.1- Optical Scan Tabulation	71	15	The Futorial Rose Fee as the Fier Rose Rose Early Forming and Election Suff.	yes
	Central Count	Model 100-5.4.4.5	1	15		,
	ADA/Touchscreen Component	Automark-1.3.2907	63	14		
Woodford	In Precinct Scan	M-100/5.4.4.5	52	11-15	Good working condition	Yes
	ADA/Touchscreen Component	Automark/1.3.2907	38	13	Good working condition	
Bloomington	In Precinct Scan	DS200/2.13.0.0.1.2&1.3	30	3	Excellent	Yes
	ADA/Touchscreen Component	Expressvote/1.4.0.0-1.0	30	3	Excellent	
		W. 500 FM 6	_	42.4	Election Management System: handles ballot production for the Insight ballot scanner, E2P touchscreen ballot, 400C central scan solution, and tally of election results for all listed and	
Chicago	System and Version Number	WinEDS EMS 4.0	1	13 Years old	associated components	Yes
	In Precinct Scan	Insight K2.16 (APX), K1.44 (HPX)	Approxiametly 3,200 UNITS	13 Years old	Precinct ballot scan solution	
	Transmission device	MPR- Memory Pack Reader 3.01	Approxiametly 30 UNITS	13 Years old	Reads the results from the Insight results memory pack directly into the WinEDS EMS	
	Central Count Scan	400C /WinETP 1.16	6 UNITS	13 Years old	Central ballot scan solution	
	Transmission device	HAAT 2.6	Approxiametly 3,200 UNITS		Consolidates and transmits elections results at the polling place for all listed associated components into the EMS for tally	
	ADA/Touchscreen Component	Edge2plus 1.2 (E2P)	Approxiametly 3,200 UNITS	13 Years old	Direct Recording Device touchscreen solution	
					S .	
	Electronic Ballot Marking Device	None	N/A	N/A	N/A	
Danville	Electronic Ballot Marking Device	None	N/A	N/A	-	ves
Danville	-				N/A	yes
Danville	In Precinct Scan	ES \$ E DS200 Unity 3411	16	2-4 yrs	N/A count Ballots	yes
Danville	In Precinct Scan ADA/Touchscreen Componet				N/A count Ballots Ballo Making Device	yes
	In Precinct Scan ADA/Touchscreen Componet Electronic Ballot Marking Device	ES \$ E DS200 Unity 3411 Automark Unity 3411	16 30	2-4 yrs 14	N/A count Ballots	
Danville E. St. Louis	In Precinct Scan ADA/Touchscreen Componet	ES \$ E DS200 Unity 3411 Automark Unity 3411 Unity ERM 3.4.1.1	16 30 30	2-4 yrs 14 14	N/A count Ballots Ballo Making Device Ballo Making Device	yes
	In Precinct Scan ADA/Touchscreen Componet Electronic Ballot Marking Device In Precinct Scan:	ES \$ E DS200 Unity 3411 Automark Unity 3411 Unity ERM 3.4.1.1 M100 Optical Scan 5.4.4.5	16 30 30	2-4 yrs 14 14	count Ballots Ballo Making Device Ballo Making Device Ballo Making Device	
	In Precinct Scan ADA/Touchscreen Componet Electronic Ballot Marking Device	ES \$ E DS200 Unity 3411 Automark Unity 3411 Unity ERM 3.4.1.1	16 30 30	2-4 yrs 14 14	N/A count Ballots Ballo Making Device Ballo Making Device	
E. St. Louis	In Precinct Scan ADA/Touchscreen Componet Electronic Ballot Marking Device In Precinct Scan: ADA/Touchscreen Component:	ES \$ E DS200 Unity 3411 Automark Unity 3411 Unity ERM 3.4.1.1 M100 Optical Scan 5.4.4.5 AutoMARK 1.3.2907	16 30 30 30 29	2-4 yrs 14 14 30 13 Years	count Ballots Ballo Making Device Ballo Making Device Ballo Making Device Election Day Precinct Scanner that Counts Ballots ADA Ballot Marking Device Machine for Early Voting &Election Day	Yes
	In Precinct Scan ADA/Touchscreen Componet Electronic Ballot Marking Device In Precinct Scan: ADA/Touchscreen Component: In Precinct Scan	ES \$ E DS200 Unity 3411 Automark Unity 3411 Unity ERM 3.4.1.1 M100 Optical Scan 5.4.4.5 AutoMARK 1.3.2907 M100 5.4.4.5	16 30 30 30 29	2-4 yrs 14 14 30 13 Years	count Ballots Ballo Making Device Ballo Making Device Ballo Making Device Election Day Precinct Scanner that Counts Ballots ADA Ballot Marking Device Machine for Early Voting &Election Day Excellent	
E. St. Louis	In Precinct Scan ADA/Touchscreen Componet Electronic Ballot Marking Device In Precinct Scan: ADA/Touchscreen Component:	ES \$ E DS200 Unity 3411 Automark Unity 3411 Unity ERM 3.4.1.1 M100 Optical Scan 5.4.4.5 AutoMARK 1.3.2907	16 30 30 30 29	2-4 yrs 14 14 30 13 Years	count Ballots Ballo Making Device Ballo Making Device Ballo Making Device Election Day Precinct Scanner that Counts Ballots ADA Ballot Marking Device Machine for Early Voting &Election Day	Yes
E. St. Louis	In Precinct Scan ADA/Touchscreen Componet Electronic Ballot Marking Device In Precinct Scan: ADA/Touchscreen Component: In Precinct Scan ADA/Touchscreen Component Unity 3.4.01	ES \$ E DS200 Unity 3411 Automark Unity 3411 Unity ERM 3.4.1.1 M100 Optical Scan 5.4.4.5 AutoMARK 1.3.2907 M100 5.4.4.5	16 30 30 30 29	2-4 yrs 14 14 30 13 Years 14yrs	count Ballots Ballo Making Device Ballo Making Device Ballo Making Device Election Day Precinct Scanner that Counts Ballots ADA Ballot Marking Device Machine for Early Voting &Election Day Excellent	Yes
E. St. Louis Galesburg	In Precinct Scan ADA/Touchscreen Componet Electronic Ballot Marking Device In Precinct Scan: ADA/Touchscreen Component: In Precinct Scan ADA/Touchscreen Component	ES \$ E DS200 Unity 3411 Automark Unity 3411 Unity ERM 3.4.1.1 M100 Optical Scan 5.4.4.5 AutoMARK 1.3.2907 M100 5.4.4.5 AutoMark 1.3.2907	16 30 30 30 29 18 15	2-4 yrs 14 14 30 13 Years	count Ballots Ballo Making Device Ballo Making Device Ballo Making Device Election Day Precinct Scanner that Counts Ballots ADA Ballot Marking Device Machine for Early Voting & Election Day Excellent Excellent	Yes
E. St. Louis Galesburg	In Precinct Scan ADA/Touchscreen Componet Electronic Ballot Marking Device In Precinct Scan: ADA/Touchscreen Component: In Precinct Scan ADA/Touchscreen Component Unity 3.4.01 ADA/Touchscreen Component	ES \$ E DS200 Unity 3411 Automark Unity 3411 Unity ERM 3.4.1.1 M100 Optical Scan 5.4.4.5 AutoMARK 1.3.2907 M100 5.4.4.5 AutoMark 1.3.2907	16 30 30 30 29 18 15	2-4 yrs 14 14 30 13 Years 14yrs 14 years	count Ballots Ballo Making Device Ballo Making Device Ballo Making Device Election Day Precinct Scanner that Counts Ballots ADA Ballot Marking Device Machine for Early Voting & Election Day Excellent Excellent Good	Yes
E. St. Louis Galesburg	In Precinct Scan ADA/Touchscreen Componet Electronic Ballot Marking Device In Precinct Scan: ADA/Touchscreen Component: In Precinct Scan ADA/Touchscreen Component Unity 3.4.01 ADA/Touchscreen Component	ES \$ E DS200 Unity 3411 Automark Unity 3411 Unity ERM 3.4.1.1 M100 Optical Scan 5.4.4.5 AutoMARK 1.3.2907 M100 5.4.4.5 AutoMark 1.3.2907	16 30 30 30 29 18 15	2-4 yrs 14 14 30 13 Years 14yrs 14 years	count Ballots Ballo Making Device Ballo Making Device Ballo Making Device Election Day Precinct Scanner that Counts Ballots ADA Ballot Marking Device Machine for Early Voting & Election Day Excellent Excellent Good	Yes